

FIELD OFFICE TECHNICAL GUIDE Sec. II  
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
1B: Ida-----	95	Not limited		Not limited		Not limited	
1C: Ida-----	95	Not limited		Not limited		Not limited	
1C3: Ida-----	95	Not limited		Not limited		Not limited	
1D: Ida-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
1D3: Ida-----	95	Very limited Water erosion	1.00	Very limited Water erosion	1.00	Somewhat limited Slope	0.63
1E: Ida-----	100	Somewhat limited Slope	0.08	Not limited		Very limited Slope	1.00
1E3: Ida-----	95	Very limited Water erosion Slope	1.00 0.08	Very limited Water erosion	1.00	Very limited Slope	1.00
1F3: Ida-----	100	Very limited Water erosion Slope	1.00 1.00	Very limited Water erosion	1.00	Very limited Slope	1.00
8B: Judson-----	95	Not limited		Not limited		Not limited	
8C: Judson-----	100	Not limited		Not limited		Not limited	
9B: Marshall-----	100	Not limited		Not limited		Not limited	
9B2: Marshall-----	95	Not limited		Not limited		Not limited	
9C: Marshall-----	100	Not limited		Not limited		Not limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II  
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
9C2: Marshall-----	95	Not limited		Not limited		Not limited	
9D: Marshall-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
9D2: Marshall-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
11B: Colo-----	50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Flooding	1.00 0.60
Judson-----	40	Not limited		Not limited		Not limited	
22D3: Dow-----	95	Very limited Water erosion	1.00	Very limited Water erosion	1.00	Somewhat limited Slope	0.63
26: Kennebec-----	90	Not limited		Not limited		Somewhat limited Flooding	0.60
26B: Kennebec-----	95	Not limited		Not limited		Somewhat limited Flooding	0.60
27B: Terril-----	100	Not limited		Not limited		Not limited	
27C: Terril-----	100	Not limited		Not limited		Not limited	
28C2: Dickman-----	100	Not limited		Not limited		Not limited	
28D2: Dickman-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
31: Afton-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
						Flooding	0.60
35E2: Steinauer-----	55	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
Burchard-----	40	Somewhat limited Slope	0.02	Not limited		Very limited Slope	1.00
35G: Steinauer-----	55	Very limited Slope	1.00	Somewhat limited Slope	0.14	Very limited Slope	1.00
Burchard-----	40	Somewhat limited Slope	0.98	Not limited		Very limited Slope	1.00
54: Zook-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Flooding	0.60
59D2: Burchard-----	95	Not limited		Not limited		Somewhat limited Slope	0.16
78B: Sac-----	95	Not limited		Not limited		Not limited	
78B2: Sac-----	95	Not limited		Not limited		Not limited	
78C: Sac-----	95	Not limited		Not limited		Not limited	
78C2: Sac-----	95	Not limited		Not limited		Not limited	
78D2: Sac-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
91B: Primghar-----	95	Not limited		Not limited		Not limited	
92: Marcus-----	100	Very limited		Very limited		Very limited	

FIELD OFFICE TECHNICAL GUIDE Sec. II  
RECREATION INTERPRETATIONS

Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
99C2: Exira-----	100	Not limited		Not limited		Not limited	
99D2: Exira-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
99D3: Exira-----	95	Very limited Water erosion	1.00	Very limited Water erosion	1.00	Somewhat limited Slope	0.63
99E2: Exira-----	100	Somewhat limited Slope	0.08	Not limited		Very limited Slope	1.00
100C: Monona-----	100	Not limited		Not limited		Not limited	
100C2: Monona-----	95	Not limited		Not limited		Not limited	
100C3: Monona-----	95	Not limited		Not limited		Not limited	
100D: Monona-----	100	Not limited		Not limited		Somewhat limited Slope	0.63
100D2: Monona-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
100D3: Monona-----	95	Very limited Water erosion	1.00	Very limited Water erosion	1.00	Somewhat limited Slope	0.63
100E: Monona-----	95	Somewhat limited Slope	0.08	Not limited		Very limited Slope	1.00
100E2: Monona-----	95	Somewhat limited Slope	0.08	Not limited		Very limited Slope	1.00

## Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
100E3: Monona-----	95	Very limited Water erosion Slope	1.00 0.08	Very limited Water erosion	1.00	Very limited Slope	1.00
100F: Monona-----	100	Very limited Slope	1.00	Not limited		Very limited Slope	1.00
100F2: Monona-----	100	Very limited Slope	1.00	Not limited		Very limited Slope	1.00
100F3: Monona-----	100	Very limited Water erosion Slope	1.00 1.00	Very limited Water erosion	1.00	Very limited Slope	1.00
133: Colo-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Flooding	1.00 0.60
133+: Colo-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Flooding	1.00 0.60
220: Nodaway-----	90	Not limited		Not limited		Somewhat limited Flooding	0.60
309: Allendorf-----	95	Not limited		Not limited		Not limited	
310: Galva-----	100	Not limited		Not limited		Not limited	
310B: Galva-----	100	Not limited		Not limited		Not limited	
310B2: Galva-----	90	Not limited		Not limited		Not limited	

## Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
310C: Galva-----	90	Not limited		Not limited		Not limited	
310C2: Galva-----	90	Not limited		Not limited		Not limited	
310D: Galva-----	90	Not limited		Not limited		Somewhat limited Slope	0.63
310D2: Galva-----	90	Not limited		Not limited		Somewhat limited Slope	0.63
428B: Ely-----	95	Not limited		Not limited		Not limited	
430: Ackmore-----	95	Not limited		Not limited		Somewhat limited Flooding Depth to saturated zone	0.60 0.19
430B: Ackmore-----	95	Not limited		Not limited		Somewhat limited Flooding Depth to saturated zone	0.60 0.19
474C: Bolan-----	95	Not limited		Not limited		Not limited	
474D2: Bolan-----	95	Not limited		Not limited		Somewhat limited Slope	0.63
475B: Arthur-----	100	Not limited		Not limited		Not limited	
475C2: Arthur-----	95	Not limited		Not limited		Not limited	
475D2: Arthur-----	100	Not limited		Not limited		Somewhat limited Slope	0.63

## Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
509: Marshall-----	100	Not limited		Not limited		Not limited	
509B: Marshall-----	100	Not limited		Not limited		Not limited	
509C: Marshall-----	100	Not limited		Not limited		Not limited	
509C2: Marshall-----	100	Not limited		Not limited		Not limited	
740C: Hawick-----	95	Not limited		Not limited		Very limited Droughty	0.94
740E: Hawick-----	95	Not limited		Not limited		Very limited Slope Droughty	0.96 0.94
740G: Hawick-----	95	Very limited Slope	1.00	Somewhat limited Slope	0.14	Very limited Slope Droughty	1.00 0.94
810: Galva-----	100	Not limited		Not limited		Not limited	
810B: Galva-----	100	Not limited		Not limited		Not limited	
810C2: Galva-----	95	Not limited		Not limited		Not limited	
1220: Nodaway-----	90	Somewhat limited Flooding	0.40	Somewhat limited Flooding	0.40	Very limited Flooding	1.00
5010: Pits-----	100	Not rated		Not rated		Not rated	

## Recreation - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Ida county, Iowa

Map symbol and soil name	Pct. of map unit	Paths and trails		Off-road motorcycle trails		Golf fairways	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
5040: Orthents-----	100	Not rated		Not rated		Not rated	
W: Water-----	100	Not rated		Not rated		Not rated	



